#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015036 Address: 333 Burma Road **Date Inspected:** 20-Jun-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG Segment** 

#### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

**OBG Trial Assembly Yard** 

Segment 8CW

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD12A-PP070-169. The welder is identified as #066413 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD10A-PP068-170. The welder is identified as #068097 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

Segment 8CE

## WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD18-PP070-169. The welder is identified as #067572 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

Counter Weight Assembly 52 and 54

This QA Inspector observed Base Metal Repair using Shielded Metal Arc Welding (SMAW) in progress at locations of removed lifting lugs on the top panel of the counter weight assembly. The welder is identified as #066261 and was observed welding in the 1G (flat) position using approved Welding Procedure Specification WPS-345-SMAW-1G (1F)-FCM-repair-1 for WR13677.

For the above mentioned welding activities ZPMC Quality Control (QC) Inspector is identified as Wang Li Yang. QA Inspector observed QC Inspector verify welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Segment 8AW

This QA Inspector observed ABF personnel performing Magnetic Particle Testing on the Deck Plate I-rib to exterior Edge Plate at panel points 63 - 64.

This QA Inspector observed removal of temporary stiffener from FL3 web exterior by flame cut at panel point 64.

Segment 7DW

This QA Inspector observed ZPMC personnel performing Magnetic Particle Testing on the FL3 Partial Height Diaphragm to FL3 I-rib stiffeners at panel point 56 to 58.

**QA** Verification

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC MT personnel. The following items were tested:

Segment 8AW/8BW

SEG043B-046

SEG043C-009

SEG045B-007

SEG045C-011

Lift 8 West

TR1B-PP61-004

TR1A-PP61-002

# WELDING INSPECTION REPORT

(Continued Page 3 of 3)

TR1A-PP69-002

TR1D-PP69-008

TR1B-PP67-004

TR2A-PP68-002

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## **Summary of Conversations:**

No relevant conversations.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer